CABLE WIRING INFORMATION

fast 🖬 heat

Fast Heat (UK) Limited, Unit 28, Hawthorn Road, Eastbourne, East Sussex, BN23 60A Tel: 01323 547375, Fax: 01323 410355, e-mail: tech-support@fastheatuk.com, web: www.fastheatuk.com

Nominal Area (mm ²)	Nearest AWG	Nominal Current Rating (A)
0.5	20	8
1.0	17	13
1.5	16	17
2.5	13 / 14	24
4.0	11 / 12	32
6.0	10	41
10.0	8	55
16.0	6	69
25.0	4	84

Wiring Recommendations

- Ensure that cable insulators are undamaged.
- Ensure that all cables are unwound and not kinked.
- Ensure that all connections are sound with no inner cables or conductors visible.
- Ensure that all conductors are of sufficient current rating for the applied load.
- Ensure that all connectors are of sufficient current rating for the applied load.
- Always protect the equipment with the correctly rated fuses.
- Always isolate equipment before removing cables from sockets.
- Cables can be damaged and due care should be taken to avoid situations in which they could be crushed, driven over, over forced or bent beyond their recommended tolerance.
- Electricity can kill. Never take electricity itself or associated equipment and appliances for granted.

Cable Colours				
Single Phase				
Country	Wire	Colour		
Europe	Live	Brown		
	Neutral	Blue		
Colour = Green / Yellow	Earth			
	-			
USA	Live	Black		
	Neutral	White		
	Earth	Green		

Three Ph	nase	
Country	Wire	Colour
Europe	Phase 1	Red
	Phase 2	Yellow
	Phase 3	Blue
	Neutral	Black
Colour = Green / Yellow	Earth	

Phase 2	Black
Phase 3	White
Earth	Green
	Phase 3

Cable Connector Colours & Wiring

